

**Request for Proposal
Addendum #1**

RFP 2017 – 009

Clarifications, Questions and Answers

For

75 Billy Bishop Way

March 16, 2017

CLARIFICATIONS ON RFP 2017-009

Build Toronto would like to provide the following clarifications to the proponents on RFP 2017-009, please read carefully:

Response to RFP Questions		
	Question	Answer
1	<p>The preliminary pylon sign elevation per the attached Appendix 2 would indicate the pylon sign is single faced where you can only change the graphic signage panels from one side.</p> <p>a. Is this a single or double sided pylon sign?</p>	<p>Both pylon signs proposed for the Site are intended to be double-sided pylon signs.</p>
2	<p>The pylon sign in the preliminary drawing is shown with brick work.</p> <p>a. Can you please specify what type of above grade brick work is required?</p>	<p>a. The exact detail of the brick treatment will be determined in collaboration with and on advice from the successful proponent.</p>
3	<p>b. The top cap or silcap is made of pre-cast concrete, stone top cap or aluminum?</p>	<p>b. The exact detail will be determined in collaboration with and on advice from the successful proponent</p>